



ETR Laboratories

WATER AND ENVIRONMENTAL TESTING

Report #: 822241629

Date : 8/22/2024

P.O.Number: 8-22-24 Visa

JFM Home Inspections
115 Country Lane
East Hartford, CT 06118-

Matrix: Water

Client: Shane Thomson

Sample 53 Peck Ln

Location: Colchester CT 06415

Phone (860) 502-4583

This sample taken by Jay at 5:30:00 PM on 8/20/2024. .
Point of collection: Kitchen Sink

Comprehensive Scan Report

<u>Analytes</u>	<u>Results</u>	<u>Accredited Method</u>	<u>EPA Limits</u>
<u>Bacteria</u>			
Total Coliform	Absent	Indicates Presence of Harmful Bacteria	0
E. Coli	Absent	Known to Cause Illness	0
<u>Mineral Chemistry</u>			
Sodium	35.33 mg/L	A Component of Salt	No Limit
Potassium	Not Detected	A Component of Salt	No Limit
Copper	0.03 mg/L	Indicates Plumbing Corrosion	1.30 mg/L
Iron	0.03 mg/L	Brown Stains, Bitter Taste	0.30 mg/L
Manganese	Not Detected	May Cause Black/ Laundry Staining	0.05 mg/L
Magnesium	Not Detected	A Component of Hardness	No Limit
Calcium	Not Detected	A Component of Hardness	No Limit
Arsenic (Total)	Not Detected	A Naturally Occurring Toxic Element	0.010 mg/L
Lead	Not Detected	A Toxic Metal, From Plumbing Components	0.015 mg/L
pH	7.23 SU	Acid/Basic Determination	6.5 - 8.5 SU
Turbidity	<0.20 N.T.U.	Presence of Particles/Measure of Cloudiness	No Limit
Color	0 C.U.	Clarity (0), Discoloration (15)	15.0 C.U.
Odor	Absent	Odor May Be Due To Bacteria Contamination	3.0 T.O.N.
Conductivity	154.0 umhos	Electrical Resistance (umhos/cm)	No Limit
T.D.S.	92.4 mg/L	Total Dissolved Minerals Present	500.0 mg/L
Sediment	Absent	Undissolved Solids	Present
Chlorine	Not Detected	A Disinfectant Byproduct	4.0 mg/L
Chloride	2.47 mg/L	A Component of Salt	250.0 mg/L
Hardness	0.0 mg/L	75 or Higher is Considered Hard	No Limit
Nitrate as Nitrogen	Not Detected	Indicator of Biological Waste	10.0 mg/L
Nitrite as Nitrogen	Not Detected	Indicator of Waste	1.0 mg/L
Ammonia as Nitrogen	Not Detected	Indicator of Waste	No Limit
Sulfate	13.95 mg/L	A Mineral, Can Cause Odor	250.0 mg/L
<u>Radiochemistry</u>			
Radon in Water	2690 pCi/L	CT DEP proposed guideline	5000 pCi/L

The integrity of the sample and results are dependent on the quality of sampling. The results apply only to the actual sample tested. Environmental Testing and Research Laboratories shall be held harmless from any liability arising out of the use of such results. Not all analyses were conducted in accordance with Massachusetts Department of Environmental Protection certification standards.



ETR Laboratories

WATER AND ENVIRONMENTAL TESTING

Report #: 822241629

Date : 8/22/2024

P.O.Number: 8-22-24 Visa

JFM Home Inspections
115 Country Lane
East Hartford, CT 06118-

Matrix: Water

Client: Shane Thomson

Sample 53 Peck Ln

Location: Colchester CT 06415

Phone (860) 502-4583

This sample taken by Jay at 5:30:00 PM on 8/20/2024. .
Point of collection: Kitchen Sink

Comprehensive Scan Report

<u>Analytes</u>	<u>Results</u>	<u>Accredited Method</u>	<u>EPA Limits</u>
<u>Volatile Organics</u>			
Benzene	Not Detected	Industrial Solvent	5.0 ug/L
Bromobenzene	Not Detected	Industrial Solvent	-
Bromochloromethane	Not Detected	Industrial Solvent	-
Bromodichloromethane	Not Detected	A Disinfectant Byproduct	-
Bromoform	Not Detected	Industrial Solvent	-
Bromomethane	Not Detected	Industrial Solvent	-
n-Butylbenzene	Not Detected	Industrial Solvent	-
sec-Butylbenzene	Not Detected	Industrial Solvent	No Limit
tert-Butylbenzene	Not Detected	Industrial Solvent	-
Carbon-Tetrachloride	Not Detected	Industrial Solvent	5.0 ug/L
Dibromochloromethane	Not Detected	A Disinfectant Byproduct	-
Chloroethane	Not Detected	Industrial Solvent	-
Chloroform	Not Detected	A Disinfectant Byproduct	-
Chloromethane	Not Detected	Industrial Solvent	-
1,2-Chlorotoluene	Not Detected	Industrial Solvent	-
1,4-Chlorotoluene	Not Detected	Industrial Solvent	-
1,2-Dibromo-3-chloropropane	Not Detected	Pesticide Byproduct	0.2 ug/L
Dibromomethane	Not Detected	Industrial Solvent	-
1,2-Dibromoethane	Not Detected	Pesticide Byproduct	-
1,3-Dichlorobenzene	Not Detected	Pesticide Byproduct	-
1,2-Dichlorobenzene	Not Detected	Pesticide Byproduct	600.0 ug/L
1,4-Dichlorobenzene	Not Detected	Pesticide Byproduct	5.0 ug/L
Dichlorodifluoromethane	Not Detected	Industrial Solvent	-
1,1-Dichloroethane	Not Detected	Plastic Manufacturing Byproduct	-
1,2-Dichloroethane	Not Detected	Plastic Manufacturing Byproduct	5.0 ug/L
1,1-Dichloroethylene	Not Detected	Plastic Manufacturing Byproduct	7.0 ug/L
cis-1,2-Dichloroethene	Not Detected	Industrial Solvent	70.0 ug/L
trans-1,2-Dichloroethene	Not Detected	Industrial Solvent	100.0 ug/L
1,2-Dichloropropane	Not Detected	Industrial Solvent	5.0 ug/L
1,3-Dichloropropane	Not Detected	Pesticide Byproduct	-
2,2-Dichloropropane	Not Detected	Industrial Solvent	-

The integrity of the sample and results are dependent on the quality of sampling. The results apply only to the actual sample tested. Environmental Testing and Research Laboratories shall be held harmless from any liability arising out of the use of such results. Not all analyses were conducted in accordance with Massachusetts Department of Environmental Protection certification standards.



ETR Laboratories

WATER AND ENVIRONMENTAL TESTING

Report #: 822241629

Date : 8/22/2024

P.O.Number: 8-22-24 Visa

JFM Home Inspections
115 Country Lane
East Hartford, CT 06118-

Matrix: Water

Client: Shane Thomson

Sample 53 Peck Ln

Location: Colchester CT 06415

Phone (860) 502-4583

This sample taken by Jay at 5:30:00 PM on 8/20/2024. .
Point of collection: Kitchen Sink

Comprehensive Scan Report

<u>Analytes</u>	<u>Results</u>	<u>Accredited Method</u>	<u>EPA Limits</u>
1,1-Dichloropropene	Not Detected	Pesticide Byproduct	-
1,3-Dichloropropene	Not Detected	Pesticide Byproduct	-
trans-1,3-Dichloropropene	Not Detected	Pesticide Byproduct	No Limit
Ethylbenzene	Not Detected	Industrial Solvent	700.0 ug/L
Trichlorofluoromethane	Not Detected	Industrial Solvent	No Limit
Hexachlorobutadiene	Not Detected	Industrial Solvent	-
Isopropylbenzene	Not Detected	Industrial Solvent	-
p-Isopropyltoluene	Not Detected	Industrial Solvent	-
Methyl-t-Butyl Ether (MTBE)	Not Detected	Gasoline Byproduct	70.0 ug/L
Methylene Chloride	Not Detected	Industrial Solvent	5.0 ug/L
Monochlorobenzene	Not Detected	Industrial Solvent	100.0 ug/L
Napthalene	Not Detected	Industrial Solvent	-
n-Propylbenzene	Not Detected	Industrial Solvent	-
Styrene	Not Detected	Plastic Manufacturing Byproduct	100.0 ug/L
1,1,1,2-Tetrachloroethane	Not Detected	Industrial Solvent	-
1,1,2,2-Tetrachloroethane	Not Detected	Industrial Solvent	-
Tetrachloroethylene	Not Detected	Industrial Solvent	5.0 ug/L
Toluene	Not Detected	Industrial Solvent	1000.0 ug/L
1,2,3-Trichlorobenzene	Not Detected	Industrial Solvent	-
1,2,4-Trichlorobenzene	Not Detected	Industrial Solvent	70.0 ug/L
1,1,1-Trichloroethane	Not Detected	Industrial Solvent	200.0 ug/L
1,1,2-Trichloroethane	Not Detected	Industrial Solvent	5.0 ug/L
Trichloroethylene	Not Detected	Industrial Solvent	5.0 ug/L
1,2,3-Trichloropropane	Not Detected	Industrial Solvent	-
1,2,4-Trimethylbenzene	Not Detected	Industrial Solvent	-
1,3,5-Trimethylbenzene	Not Detected	Plastic Manufacturing Byproduct	-
Vinyl Chloride	Not Detected	Plastic Manufacturing Byproduct	2.0 ug/L
o-Xylene	Not Detected	Industrial Solvent	T. Xylenes 10K ug/
m+p Xylenes	Not Detected	Industrial Solvent	T. Xylenes 10K ug/

The integrity of the sample and results are dependent on the quality of sampling. The results apply only to the actual sample tested. Environmental Testing and Research Laboratories shall be held harmless from any liability arising out of the use of such results. Not all analyses were conducted in accordance with Massachusetts Department of Environmental Protection certification standards.